B.R. No: 661/Date: 29/03/2014

Annual.

Inspection report for the work of : Maintenance of borewell of Chikkasandra & Medarahalli, in Dasarahalli Zone

By

Sri. *G.M. Muniyappa*

Inspection Report

Name of Work		Annual Maintenance of borewell of Chikkasandra & Medarahalli, in Dasarahalli Zone
Work Order	:	No. EE/DD/WO/ 157/13-14, Dated: 12/12/2013
Agency	:	S. Prakash
B.R. No & Dated	:	661/Date: 29/03/2014
Bill Amount	:	Rs. 1452513.00
Job Code	:	012-13-000040
P. Code	:	P1771

Date of Inspection :- 29-08-14

The above said Work - Maintenance of Bore Wells of Chikkasandra & Medarahalli in Dasarahalli Zone - have been shown by the Concerned AE. The above said work have been inspected along with the Concerned AE the Water Supply to the Residents of the Vicinity of the Bore Wells is running Smoothly. The log book pertains to the Maintenance of Bore Wells is maintained. The Register pertains to repairs of pump sets and Bore Wells is Verified. The Concerned file is Verified. The pertains to the "BESCOM" The work done is Satisfactory

Ravi.N.K.
AE W-12

16

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಶಿವಾಜಿನಗರ ವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ,
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

G.M.MUNIYAPPA,
B.E.(ELECT) B.E. (CIVIL)
EXECUTIVE ENGINEER (TD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57.

Name of Work : Annual Maintenance of borewell of Chikkasandra & Medarahalli, in Dasarahalli Zone

Ravi. N.K.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ,
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57.